

Update Date: Feb 2010

GENERAL DETAILS

Fleet No.:	<u>FC01</u>	Serial No.:	<u>3076</u>	Tonnes:	<u>16</u>
Make:	<u>Franna</u>	Model:	<u>AWD 16</u>	Chassis No:	<u></u>
Year:	<u>1994</u>	Rego. No.:	<u>TLW 619 – Vic</u>	Engine No:	<u></u>

CARRIER (LOWER STRUCTURE)

Airconditioning:	<u>Main Cabin: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>	
Tyre Size:	<u>12.00</u>	
Tyre Condition:	<u>100% Front / 50% Rear</u>	
Outrigger Type:	<u>NA – Articulated – Joint Good</u>	
Front Outrigger Fitted:	<u>Yes <input type="checkbox"/> No <input type="checkbox"/> NA</u>	
Carrier Make:	<u>Franna</u>	
Carrier Kilometres:	<u>151,737</u>	
Engine Make:	<u>HINO</u>	
Engine: No. of Cylinders:	<u>6</u>	
Crane Engine Hours:	<u>17,092</u>	
Carrier Engine Hours:	<u>As above</u>	
Is Hi Range fitted:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> - normal Hi / Lo – 2wd / 4wd Aux Trans – C/O Box fitted</u>	
Transmission Type:	<u>Auto <input checked="" type="checkbox"/> Semi Auto <input type="checkbox"/> Manual <input type="checkbox"/></u>	
Accessories:	<u>Spreader Bar</u>	
Registration:	<u>Plant Reg: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> State: Vic Road Reg: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> State: Vic</u>	
Crane Safe:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiry:</u>	



CRANE (UPPER STRUCTURE)

Articulated Joint Condition:	<u>Good</u>
Winch:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>
Length of Main Boom (under hydraulic power):	<u>17.9m – with manual</u>
Fitted with computerised lifting gauges:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> - Robway System</u>
Fly Jib Type (slung around or other):	<u>NA</u>
Fly Jib Length:	<u></u>
Number of degree offsets:	<u></u>
Hydraulic Luffing Fly:	<u>Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></u>
Rooster Sheave:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> ** Rhino Hook</u>
Hook Block:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> - Main</u>
Airconditioning:	<u>Cabin: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>

CONDITION (Full service history available on request)

Overall condition (panels, rust, etc):	<u>Excellent</u>
Painted:	<u>HMC Colors – 2 pack & good Cond</u>
Comments:	<u>Unit is an excellent example and requires nothing spent for use</u>

For more information contact:

Sales Office: (03) 8545 2000
Ron Atkins 0408 012 254
Keith Kelton 0418 559 950