

Update Date:

GENERAL DETAILS

Fleet No.:	<u>HT12</u>	Serial No.:	<u>340789</u>	Tonnes:	<u>25</u>
Make:	<u>Tadano</u>	Model:	<u>TL250M5</u>	Chassis No.:	<u></u>
Year:	<u>1998</u>	Rego. No.:	<u>RNQ 410 - Vic</u>	Engine No.:	<u></u>

CARRIER (LOWER STRUCTURE)

Airconditioning:	<u>Main Cabin: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>	
Tyre Size:	<u>1100</u>	
Tyre Condition:	<u>80% +</u>	
Outrigger Type:	<u>Out & Down</u>	
Front Outrigger Fitted:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>	
Carrier Make:	<u>Mitsubishi</u>	
Carrier Kilometres:	<u>125000</u>	
Engine Make:	<u>Mitsubishi</u>	
Engine: No. of Cylinders:	<u>8</u>	
Crane Engine Hours:	<u>Approx 9500</u>	
Carrier Engine Hours:	<u>As above</u>	
Is Hi Range fitted:	<u>Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></u>	
Transmission Type:	<u>Auto <input type="checkbox"/> Semi Auto <input type="checkbox"/> Manual <input checked="" type="checkbox"/></u>	
Accessories:	<u>Spare Wheel</u>	
Registration:	<u>Plant Reg: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> State: Vic Road Reg: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> State: Vic</u>	
Crane Safe:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiry: Oct 09</u>	



CRANE (UPPER STRUCTURE)

Slewing Ring Condition:	<u>Good</u>
Auxiliary Winch:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>
Length of Main Boom (under hydraulic power):	<u>33m</u>
Fitted with computerised lifting gauges:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>
Fly Jib Type (slung around or other):	<u>Under Slung</u>
Fly Jib Length:	<u>14.5m</u>
Number of degree offsets:	<u>5 / 15 / 30</u>
Hydraulic Luffing Fly:	<u>Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></u>
Rooster Sheave:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>
Hook Block:	<u>Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> - Main & Aux</u>
Airconditioning:	<u>Slewing Cabin: Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></u>

CONDITION (Full service history available on request)

Overall condition (panels, rust, etc):	<u>Perfect</u>
Painted:	<u>HMC Colors – 2 pack & perfect</u>
Comments:	<u>Unit is an excellent example and requires nothing spent for use</u>

For more information contact:

Sales Office: (03) 8545 2000
Ron Atkins 0408 012 254
Keith Kelton 0418 559 950